



Construction Report 08/31/18


## **This Week**

#### August 27<sup>th</sup> – August 31<sup>st</sup>, 2018

- Sheetrock Corridors Area A and B 2<sup>nd</sup> Floor
- Install Window Frames Area A
- Install Windows Area A
- Exterior Stone and Brick Area A
- Hang Ceiling Grid Area A & B
- Setting Casework in Area A & B
- Carpet in Classroom Area B
- Install Restroom Accessories Area A & B
- Hang Lighting Fixtures in Area A & B
- Interior Painting Areas A & B
- Install Kitchen Equipment Area C
- Tectum Panels in Gym
- Polish Concrete Areas A & B 1<sup>st</sup> Floor Corridor
- Base Coat Asphalt East Parking Lot



Base Coat Asphalt East Drive and Parking Lot



## Next Week

### September 4<sup>th</sup>- Sept. 7<sup>th</sup>, 2018

- Sheetrock Corridor Area A
- Exterior Stone and Brick Area A
- Install Window Frames in Area A
- Install Windows in Area A
- Hang Ceiling Grid Area A
- Court Markings Gym Floor Area D
- Install Bleachers in Gym Area D
- Setting Casework in Area A
- Interior Painting- Areas A & B
- Install Carpet in Classrooms Area A
- Install Playground Equipment
- Site work on West side



Exterior Stone & Brick, Window Frame & Window Installation on East Side of Area A



Brookwood Elementary Bi-Weekly Construction Report

# Brookwood Elementary School Construction Report 08/31/18







Classroom Area B – Casework, Carpet, Ceiling Grid

Tectum Panels in Gym Area D





Collaboration Spaces / Soffits on 2<sup>nd</sup> Floor Area A

Concrete Curbs and Rock for Soft Play Area and Rock for Hard Play Area



Brookwood Elementary Bi-Weekly Construction Report